



**ENTRUST**

Time Stamp Option Pack

# TSOP v8.0.0 Release Notes

10 April 2024

# Table of Contents

1. Introduction .....	1
2. Purpose of this release .....	3
3. Changes in this release .....	4
3.1. Support for the Solo XC .....	4
3.2. Other changes .....	4
4. Important Information .....	5
5. Known issues .....	6

# 1. Introduction

These release notes apply to version 8.0.0 of the Time Stamp Option Pack™ (TSOP). They contain information specific to this release such as new features, defect fixes, and known issues.

This release supports the following operating systems:

- Microsoft Windows Server 2012 R2 x64
- Microsoft Windows Server 2016 x64
- Microsoft Windows Server 2019 x64

With the following nShield Hardware Security Modules (HSMs):

- nShield Solo 500+ F3 for TSOP
  - Supporting 2.61.4, 12.40.0, 12.50.8 (FIPS approved), 12.60.2, 12.70.2, 12.72.0 (FIPS approved) or 12.80.2 firmware with v12.40, v12.60, v12.70 and v12.80 Security World Software.
- nShield Solo XC Base F3 for TSOP
  - Supporting 12.70.8, 12.72.1 (FIPS approved) or 12.80.5 firmware with v12.70 and v12.80 Security World Software.



New installations may need to upgrade their firmware from the version shipped to one listed above.



If you do not wish to reconfigure your Time Stamp Server™ (TSS), or if your Time Stamping Authority (TSA) keys were not protected using an operator cardset, you should not upgrade your firmware or attempt to replace your existing HSM.



This release of TSOP has only been tested with the above firmware and Security World Software versions.



If using 12.72.0 or 12.72.1 firmware, please consult the *12.72 FIPS Firmware Release* release notes.

The Release Notes may from time to time be updated with issues that have come to light after this release has been made available. Please check Entrust nShield Support at <https://nshieldsupport.entrust.com> for the most up to date version of this document and the TSOP user documentation.

Access to support is available to customers under maintenance. Please contact Entrust

nShield Support at [nShield.support@entrust.com](mailto:nShield.support@entrust.com) to request an account.

## 2. Purpose of this release

Time Stamp Option Pack™ version 8.0.0 addresses a number of known issues and introduces a number of enhancements over the previous 7.20.0 release, including:

- Support for the Solo XC.

## 3. Changes in this release

The TSOP 8.0.0 release introduces a number of enhancements. These are discussed in the following sections.

### 3.1. Support for the Solo XC

TSOP now supports the Solo XC hardware security module variant. See [Introduction](#) for the supported Security World and firmware versions.

### 3.2. Other changes

Other changes include:

- Several third-party dependencies have been updated.

## 4. Important Information

Before deploying the TSOP, the following should be considered:

- This release only supports the operating systems detailed in [Introduction](#).
- Before attempting to create a Security World, it is necessary to install the **SEE Activation (Restricted)** feature certificate, otherwise the keys will not be created correctly for the SEE machine. Similarly, the **Elliptic Curve algorithms** feature certificate should be installed to allow the generation of ECDSA-based TSA keys.
- When using `new-world` to generate a Security World, ensure that the `dseeall` feature is specified. On completion of world generation, it will be necessary to perform SEE delegation - see [Security World: SEE delegation](#).
- Before upgrading an existing TSOP deployment, ensure that the files within `%NFAST_HOME%\dse200\UserFiles` are backed up.
- If you require the ability to back up and restore a TSA key, you must use OCS protection. See [Creating Operator Card Sets](#).
- When performing a firmware upgrade on an existing TSOP deployment, or attempting to replace the HSM, much of the TSOP configuration will be lost and will have to be set-up again through the TSOP web interface. Specifically, please note that:
  - TSA keys will be lost, unless they were generated with the Operator Card-Set backup option (see [Restoring a TSA key](#)).
  - TSA configuration will be lost.
- If you do not wish to reconfigure your TSOP deployment, or if your TSA keys are not protected using an operator cardset, you should not upgrade your firmware or replace your HSM.
- This release of TSOP has been tested with the firmware versions detailed in [Introduction](#) only.
- If continuing to use the firmware shipped with the 5.10.01 and 6.00.00 releases (2.38.7 and 2.61.4 respectively), it will not be possible to generate an ECDSA-based TSA key using the SECP256k1 curve. This curve is only supported from 12.40.0 firmware.
- If a TSA reports **TAC\_Invalid**, and the clock status for that TSA shows as being **Disabled**, it might be necessary to re-set the module clock. This can be confirmed by consulting the board log and looking for entries such as **exceeded 4 seconds per day**. See the *Enabling or disabling the clock* section of the *TSOP Administrator Guide* for further information.

## 5. Known issues

This release includes the following known issues:

- If the SEE Delegation is not set up correctly, this can result in errors whose cause is not obvious. If you are getting unexplained errors and the board log includes messages about **NVRam failure**, **RTC failure**, or **Key Generation failure**, these are likely to have been caused by a **DSEDelegation** error.
- **Fatal Error: Java Failure, com.ncipher.km.nfkm.SecurityWorld object initialization failure** is displayed if `nonpriv_port` and `priv_port` are not set within the hardserver's config file. These ports can be set by running: `config-serverstartup.exe --port 9000 --privport 9001` or by editing the file (located at `%NFAST_KMDATA%\config\config`) and setting `nonpriv_port=9000` and `priv_port=9001` (substituting the port numbers as appropriate). It is then necessary to restart the hardserver (which, in turn, will restart the DSE200 service).
- If the TSS is very busy responding to time-stamp requests during a DSNTTP audit, the DSNTTP audit will likely fail with a large communication delay.
- If using 12.70.2 or 12.80.2 firmware, when in a FIPS 140-2 Level 3 Security World, both DSE200 service start up time and individual audit requests will take longer due to additional key generation checks being performed on clock audit.
- When a DSNTTP port is entered for a TSA, the TSS does not verify if that port is already in use by another process.
- If using a version of Java impacted by JDK-8191040, it will be necessary to either move to a different version or to apply the documented workaround, see [https://bugs.java.com/bugdatabase/view\\_bug.do?bug\\_id=8191040](https://bugs.java.com/bugdatabase/view_bug.do?bug_id=8191040) for more information.