Chapter

Release Notes: nShield Security World v13.9.9 Release Notes

Table of Contents

1. Introduction . . . 2
    1.1. Updated nShield Software Release Policy . . . 2
    1.2. Purpose of Security World v13.9 . . . 3
    1.3. Versions of these Release Notes . . . 3
2. Product versions . . . 3
    2.1. Security World software versions . . . 3
    2.2. CodeSafe Developer software versions . . . 4
    2.3. Firmware and Connect ISO versions . . . 4
    2.4. Connect image versions . . . 4
3. Features of Security World v13.9 STS Release 5 . . . 4
    3.1. Upgrade Bootloader (uboot) on nShield 5c (NSE-62695) . . . 4
    3.2. nCipher JCE provider: ML-DSA enhancements (NSE-78843) . . . 5
    3.3. ML-KEM support in JCE (NSE-64742) . . . 5
    3.4. SLH-DSA support in JCE (NSE-64743) . . . 6
    3.5. nShield Container support in Security World (NSE-53023) . . . 6
        3.5.1. New Container client license (NSE-68773) . . . 7
    3.6. HSM Healthcheck application (NSE-66866) . . . 7
    3.7. Remote Administration Client support for Apple Silicon platforms (NSE-37568) . . . 8
    3.8. CodeSafe 5 auto-load on the 5c using FIPS v13.4.5 firmware (NSE-79383) . . . 8
    3.9. New v13.9.8 Connect Images . . . 8
        3.9.1. `seeconf` keys encryption issue on nShield Connect XC and Solo XC . . . 8
    3.10. Signed ISO images (NSE-19233) . . . 9
    3.11. Open Source Software Updates in Security World v13.9 STS Release 5 . . . 9
4. Deprecated and discontinued features . . . 10
5. Firmware images . . . 10
    5.1. nShield 5s firmware . . . 10
        5.1.1. nShield 5s firmware . . . 10
    5.2. Solo XC firmware . . . 11
    5.3. nShield Edge Firmware . . . 11
6. Connect images . . . 11
    6.1. Install a Connect image . . . 11
    6.2. nShield 5c images . . . 11
    6.3. Connect XC images . . . 12

7. Upgrade from previous releases . . . 12
7.1. Install 13.9.9 Security World Software . . . 12
7.2. Upgrade Solo XC firmware . . . 13
7.3. Upgrade nShield 5s HSM Firmware . . . 13
7.3.1. nShield 5s Firmware Version Check . . . 14
7.3.2. Upgrading the nShield 5s Primary & Recovery Image . . . 14
7.3.3. Upgrading the nShield 5s Bootloader . . . 14
7.4. Upgrade a Connect XC image . . . 15
8. Compatibility . . . 15
8.1. Supported hardware . . . 15
8.2. Supported operating systems . . . 16
8.3. Supported operating systems for the Remote Administration Client (RAC) . . . 16
8.4. API support . . . 17
8.4.1. Java . . . 17
8.4.2. Python . . . 17
8.5. Supported hypervisors and virtual environments . . . 17
8.6. Supported compilers for Microsoft Windows C developers . . . 18
9. Known and fixed issues . . . 19

1. Introduction

These release notes apply to the release of version v13.9.9 of Security World for the nShield family of Hardware Security Modules (HSMs).

These release notes contain information specific to this release such as new features, defect fixes, and known issues. They may be updated with issues that have become known after this release has been made available. For the latest version, see https://trustedcare.entrust.com/. Access to the Support Portal is available to customers under maintenance. To request an account, contact nshield.support@entrust.com.

We continuously improve the user documents and update them after the general availability (GA) release. Changes in the document set are recorded in these release notes and are published at https://nshielddocs.entrust.com.

1.1. Updated nShield Software Release Policy

Entrust has recently introduced an update to the nShield Software release policy to better define the type of release and the associated update and support policy. As part of this, the concept of Long Term Support (LTS) and Standard Term Support (STS) software releases

has been introduced, with each software release being either a LTS or STS release.

For more information on the software release policy, see the nShield Security World Release Information. Alternatively contact https://trustedcare.entrust.com/ for more information.

1.2. Purpose of Security World v13.9

Security World version v13.9 introduces new features and enhancements as described in Features of Security World v13.9 STS Release 5. It also corrects a number of defects that have been identified in earlier releases.



Security World 13.9.9 is a **Standard-Term Supported (STS)** release. This release is designed to give early access to new nShield features and has a shorter support period.
For long-term support (LTS), frequent stability updates and certified firmware, it is recommended to use the v13.6 Long-Term Support release. See the nShield Security World Release Information for details of the supported versions and the STS & LTS policy.

This release contains updates to the following products:

- Updated Security World Software
- Updated Codesafe 5 SDK
- Updated Connect images for nShield 5c and Connect XC

1.3. Versions of these Release Notes

Revision	Date	Description
1.0	2026-10-30	Release notes for the release of v13.9.9, Security World v13.9 STS Release 5.

2. Product versions

2.1. Security World software versions

Version	Date	Description
v13.9.9	2026-11-09	Full Release of the 13.9.9 Linux and Windows ISOs.

2.2. CodeSafe Developer software versions

Version	Date	Description
v13.9.9	2026-11-09	Full Release of the 13.9.9 CodeSafe Linux and Windows ISOs.

2.3. Firmware and Connect ISO versions

Version	Date	Description
v13.9.9	2026-11-09	Full Release of the v13.9.9 FW ISO including the updated 13.9 Connect images and the Security World v13.9 STS Release 4 13.8 firmware.

2.4. Connect image versions

Version	Date	Description
v13.9.9	2026-11-09	Full Release of Security World 13.9 images for nShield 5c and nShield Connect XC HSMs containing the latest features and fixes.

3. Features of Security World v13.9 STS Release 5

3.1. Upgrade Bootloader (uboot) on nShield 5c (NSE-62695)

Security World v13.9 STS Release 5 introduces the ability to upgrade the nShield 5s Bootloader (uboot) inside the nShield 5c.

In previous releases the nShield 5s Bootloader would remain locked at the level shipped dur ing the production phase for the nShield 5c unit.

Security World v13.9 STS Release 5 now delivers the newly FIPS Certified v14.2.2 Bootloader image on nShield 5c units **only**.

During the nShield 5c upgrade process to the new Security World v13.9 STS Release 5 nShield 5c image the v14.2.2 Bootloader will be automatically loaded onto the nShield 5s unit.

Once the Security World v13.9 STS Release 5 nShield 5c image has been loaded, the

nShield 5s Bootloader version should display as: `14.2.2-0-23012d8f`.

3.2. nCipher JCE provider: ML-DSA enhancements (NSE-78843)

Security World v13.9 STS Release 5 introduces several ML-DSA-related enhancements to the nCipher JCE provider.

The following additional signature variants are now available:

- `ML-DSA-EXTERNAL-MU`
- `ML-DSA-EXTERNAL-MU-DET`
- `SHA256withML-DSA`
- `SHA256withML-DSA-DET`
- `SHA256withML-DSA-44`
- `SHA256withML-DSA-44-DET`
- `SHA256withML-DSA-65`
- `SHA256withML-DSA-65-DET`
- `SHA256withML-DSA-87`
- `SHA256withML-DSA-87-DET`

It is also now possible to import ML-DSA private keys by seed only.

Use of ML-DSA requires a firmware version of v13.8 or greater and the `PostQuantum` feature to be enabled, see the *User Guide* for your HSM for more information. See the *nCipherKM JCA JCE CSP API Guide* for further information on ML-DSA.

3.3. ML-KEM support in JCE (NSE-64742)

Security World v13.9 STS Release 5 updates the nCipherKM JCE provider to now support ML-KEM key generation, encapsulation, and decapsulation.

The following parameter sets defined by FIPS 203 are supported:

- `ML-KEM-512`
- `ML-KEM-768`
- `ML-KEM-1024`

Use of ML-KEM requires a firmware version of v13.8 or greater and the `PostQuantum` feature to be enabled, see the *User Guide* for your HSM for more information. See the *nCipherKM*

JCA JCE CSP API Guide for further information on ML-KEM.



JAVA 17 limitation `javax.crypto.KEM` was introduced in Java 21, so ML-KEM encapsulation and decapsulation through that API is not available on Java 17. ML-KEM key generation (`KeyPairGenerator` and `KeyFactory`) remains available on Java 17.

3.4. SLH-DSA support in JCE (NSE-64743)

Security World v13.9 STS Release 5 updates the nCipherKM JCE provider to now support SLH-DSA key generation, signing, and verification.

The following parameter sets defined by FIPS 205 are supported:

- `SLH-DSA-SHA2-128F`
- `SLH-DSA-SHA2-128S`
- `SLH-DSA-SHA2-192F`
- `SLH-DSA-SHA2-192S`
- `SLH-DSA-SHA2-256F`
- `SLH-DSA-SHA2-256S`
- `SLH-DSA-SHAKE-128S`
- `SLH-DSA-SHAKE-128F`
- `SLH-DSA-SHAKE-192S`
- `SLH-DSA-SHAKE-192F`
- `SLH-DSA-SHAKE-256S`
- `SLH-DSA-SHAKE-256F`

Use of SLH-DSA requires a firmware version of v13.8 or later with the `PostQuantum` feature enabled. For more information, see the *User Guide* for your HSM.

See the *nCipherKM JCA JCE CSP API Guide* for additional information on SLH-DSA.

3.5. nShield Container support in Security World (NSE-53023)

Security World v13.9 STS Release 5 introduces a rework of how the nShield Containers are supported.

nShield Containers are integrated into Security World as an installable `.tar.gz` or `.rpm` file

on Linux platforms only.

The new names and locations of the `.tar.gz` and `.rpm` files on the `SecWorld_Lin64` ISO are as follows:

- `/linux/amd64/containers.tar.gz`
- `/linux-rpms/amd64/nShield-containers-13.9.x-x.x.x86_64.rpm`

Template Dockerfiles are now shipped inside the packages and can be built using a builder tool or natively via Docker.

The new tools are more flexible and lightweight, and can be used in a Kubernetes deployment.



All supplied example files should be reviewed and secured to ensure they meet applicable security requirements.

3.5.1. New Container client license (NSE-68773)

Security World v13.9 STS Release 5 introduces client licence support for nShield Container support in Security World (NSE-53023).

The multiplier allows crypto client licenses to be exchanged for multiple container-based clients based on the multiplier license that has been purchased.

The following is an example of when container multiplier license of **10** is applied:

No. of regular hardserver connections per HSM	No. of hardserver containers per HSM	Total client licenses used
3	0	3
2	10	3
1	20	3
0	30	3

3.6. HSM Healthcheck application (NSE-66866)

Security World v13.9 STS Release 5 introduces a new lightweight utility for checking the health of HSMs called: `healthcheck`.

`healthcheck` can be used to:

- quickly verify if there is at least 1 working HSM
- if all HSMs are healthy
- a specific HSM is healthy

3.7. Remote Administration Client support for Apple Silicon platforms (NSE-37568)

Security World v13.9 STS Release 5 introduces support for Apple Silicon platforms.

Refer to [nshield-security-world-v13-9-9-release-notes:::rac_support] for supported Operating Systems.

3.8. CodeSafe 5 auto-load on the 5c using FIPS v13.4.5 firmware (NSE-79383)

Security World v13.9 STS Release 5 now supports the use of the CodeSafe 5 auto-load feature on the nShield 5c using the Latest FIPS Certified v13.4.5 firmware.

3.9. New v13.9.8 Connect Images

The nShield 5c and nShield Connect XC FIPS image is now included on the firmware ISO, this image contains the Latest FIPS Certified firmwares for the nShield 5s and nShield Solo XC.

Refer to Connect images for more information about the v13.9.8 Connect images.

Refer to Known and fixed issues for more information about fixed issues in the v13.9.8 Connect images.



When 'seejobs_transport=plain' is used with Codesafe5 machines that disallow this form of communication, the 5c will then not allow any form of communication with this SEE machine until the 5c unit is rebooted.

3.9.1. `seeconf` keys encryption issue on nShield Connect XC and Solo XC

For nShield Connect XC and Solo XC only:

- Freshly generated `seeconf` keys for SEE machine encryption created using `generatekey` in this release are not supported by the `tct2` command.

- `seeconf` keys generated in earlier releases can be used to encrypt SEE machiens with no issues when using `tct2`.
- There is no impact on loading existing encrypted SEE machines on the XC.

3.10. Signed ISO images (NSE-19233)

Starting with Security World v13.9 STS Release 5, all ISO images, including Security World, CodeSafe, Remote Administration Client, and firmware ISOs, are signed with the Entrust OpenPGP release key. This allows you to verify that the media originated from Entrust and has not been altered.

- `<image>.iso.asc` is supplied alongside each ISO image and covers the image as a whole.
- `SHA256SUMS`, `SHA256SUMS.asc` and `pubkey.asc` are in the top-level folder of each ISO image. `SHA256SUMS` lists the SHA-256 digest of each file on the media, and `SHA256-SUMS.asc` contains its signature. Use these files to verify a mounted image, a disc, or a copy of the media's files, even when `<image>.iso.asc` is unavailable.

The fingerprint of the release key is `DC17ECB0C55280DA006B60F6225FC6BC0347CDCF`. Check the key against this fingerprint, not against the copy of `pubkey.asc` on the media.

After successfully verifying a signature, GnuPG warns that the key is not certified with a trusted signature. This warning is expected. Confirm instead that the fingerprint in the output matches the one above.

For the full procedure, see *Verify the installation media* in the *Installation Guide*.

3.11. Open Source Software Updates in Security World v13.9 STS Release 5

Consult the following documents on the ISOs for Open Source Software version information in Security World v13.9 STS Release 5.

Component	PDF	ISO(s)
nShield 5s	5s-licenses.pdf	nShield_HSM_Firmware
nShield Solo XC	soloxc-licenses.pdf	nShield_HSM_Firmware
nShield 5c	connect-licenses.pdf	nShield_HSM_Firmware
nShield Connect XC	connect-licenses.pdf	nShield_HSM_Firmware

Component	PDF	ISO(s)
Security World Software	secworld-licenses.pdf	SecWorld_Lin64 / SecWorld_Windows
Security World Software Python Packages	secworld-python-licenses.pdf	SecWorld_Lin64 / SecWorld_Windows / nShield-_HSM_Firmware

4. Deprecated and discontinued features

The following features are deprecated or discontinued in Security World v13.9. If you have been using these features, plan for a new configuration and workflow that does not make use of the feature:

- KeySafe
  This is the legacy Java application. **KeySafe 5** continues to be supported in v13.9. KeySafe information has been removed from the user documentation for v13.9 and later releases. Previous user documentation releases that cover KeySafe continue to be available at https://nshielddocs.entrust.com/.

5. Firmware images

5.1. nShield 5s firmware

The nShield 5s HSM firmware consists of 3 major components:

- Primary Image
- Recovery Image
- Bootloader

The firmware for Security World v13.9 STS Release 5 only updates the Primary image. The Recovery image and Bootloader can be kept at previously released versions.

Details on what the components are used for and how to upgrade the different components are detailed in Upgrade nShield 5s HSM Firmware. Read this section prior to upgrading any nShield 5s.

5.1.1. nShield 5s firmware

Type	Version	Description	Directory	VSN
Latest	13.8.6	Firmware with features from the v13.9 STS Release 4.	`firmware/nShield5s/latest/nShield5s-13.8.6-vsn6.npkg`	6

5.2. Solo XC firmware

Type	Version	Description	Directory	VSN
Latest	13.8.5	Firmware with features from the v13.9 STS Release 4.	`firmware/SoloXC/latest/soloxc-13.8.5-vsn37.nff`	37

5.3. nShield Edge Firmware

There is no updated nShield Edge firmware being made available with the v13.9 release.

6. Connect images

The nShield firmware and Connect Image ISO includes v13.9.8 Connect images that contain the Solo XC and nShield 5s firmware described in Firmware images.

6.1. Install a Connect image

As part of the Security World installation, the `/opt/nfast/nethsm-firmware` directory is created, but it is empty. When the Connect image that needs to be installed has been chosen, the subdirectory and the image should be copied from the nShield firmware and Connect ISO into the `/opt/nfast/nethsm-firmware` directory and installed onto the Connect as usual.

6.2. nShield 5c images

Type	Version	Description	Firmware included	Directory	VSN
Latest	v13.9.8	13.9 nShield 5c image with the v13.9 STS Release 4 nShield 5s 13.8 firmware	13.8.6	`nethsm-firmware/latest-all-13.9.8-vsn33/`	33

Type	Version	Description	Firmware included	Directory	VSN
FIPS	v13.9.8	13.9 nShield 5c image with the Latest FIPS Certified nShield 5s 13.4 firmware	13.4.5	`nethsm-firmware/fips-all-13.9.8-vsn33/`	33



For security reasons the Version Security Number (VSN) of the nShield 5c image has been increased to 33. Upon updating to the new images it will **not** be possible to downgrade to previous releases.

The following releases **can** be updated to post this change:

- v13.6.12 LTS Update 4 and later

6.3. Connect XC images

Type	Version	Description	Firmware included	Directory	VSN
Latest	v13.9.8	13.9 Connect XC image with the v13.9 STS Release 4 Solo XC 13.8 firmware	13.8.5	`nethsm-firmware/latest-all-13.9.8-vsn33/`	33
FIPS	v13.9.8	13.9 Connect XC image with the Latest FIPS Certified Solo XC 12.72 firmware	12.72.4	`nethsm-firmware/fips-all-13.9.8-vsn33/`	33



For security reasons the Version Security Number (VSN) of the nShield Connect XC image has been increased to 33. Upon updating to the new images it will **not** be possible to downgrade to previous releases.

The following releases **can** be updated to post this change:

- v13.6.12 LTS Update 4 and later

7. Upgrade from previous releases

7.1. Install 13.9.9 Security World Software

Before installing this release, you must:

- Confirm that you have a current maintenance contract that licenses you to deploy

upgrades on each nShield HSM and corresponding client operating system.

- Uninstall previous releases of Security World Software from the client machines.

For instructions, see the *Installation Guide* for your HSM.

7.2. Upgrade Solo XC firmware

The following are important notes to observe when upgrading the Solo XC firmware to the latest version:

If the Solo XC HSM is installed with the earlier 3.3.10 firmware it cannot be upgraded directly to the latest firmware and needs to be first upgraded to an intermediate version. Please contact nshield.support@entrust.com and request the firmware upgrade patch from 3.3.10 to 3.3.20.

If the Solo XC HSM is installed with firmware earlier than 12.50.7, 12.50.2, 3.4.2 or 3.3.41 it cannot be upgraded directly to the latest firmware and needs to be first upgraded to an intermediate version. Any of the firmware versions listed above can be used as an intermedi ate version. Please contact nshield.support@entrust.com for any other version of firmware.



Whilst every effort is made to ensure Solo XC firmware compatibility with all mainstream hardware and virtualized environments as well as operating systems there may be occasions where a particular configura tion is not compatible (either through current version or after upgrading to a newer version of the firmware). Please contact nshield.sup- port@entrust.com if you experience any issues following an upgrade or during integration activity.

7.3. Upgrade nShield 5s HSM Firmware

As detailed in the *nShield v13.9.5 HSM User Guide*, the nShield 5s HSM firmware consists of 3 major components:

- Primary Image
- Recovery Image
- Bootloader

During normal operation, the nShield 5s is running firmware that is loaded from the Primary image. If required, the nShield 5s can be forced into recovery mode to run firmware loaded from the Recovery image. The main purpose of recovery mode is to allow essential mainte- nance activities that are not possible when the nShield 5s is running the primary image

firmware.

7.3.1. nShield 5s Firmware Version Check

Following the upgrade, the nShield 5s primary image, recovery image and bootloader versions can be checked using the `hsmadmin` command:

```
hsmadmin status --json
```

As an example, following an upgrade, it should report as follows:

```
"mode": "primary",
"primary-version": "13.8.6-295-14a66c55",
"recovery-version": "13.5.0-0-e2ec16eefd",
"uboot-version": "1.4.1-0-edb84d6e",
```

7.3.2. Upgrading the nShield 5s Primary & Recovery Image

Upgrade packages may contain updates for any of these components. The same upgrade method is used in all cases. The system will automatically detect which components are included in the update package and will load the firmware to the correct location.

It is not recommended to upgrade both the Primary and Recovery images at the same time. The recommended procedure is to upgrade the Primary firmware first. Test that the system performs as expected and then upgrade the Recovery firmware at a later date.

The primary and recovery images can be upgraded using the following command:

For primary:

```
hsmadmin upgrade nShield5s-13.8.6-vsn5.npkg --esn module-esn
```

and for recovery:

```
hsmadmin upgrade nshield5s-recovery-13-5-0.npkg --esn module-esn
```

7.3.3. Upgrading the nShield 5s Bootloader

The bootloader is the program that boots the HSM and loads the main application. The nShield 5s has a discrete bootloader that can be updated independently of the Primary and Recovery images.

7.3.3.1. Pre-Requisites

Whilst the bootloader is an independent part of the firmware, the capability to upgrade the bootloader on the nShield 5s was introduced as part of the Security World v13.4 firmware release. For earlier versions of firmware prior to v13.4, the nShield 5s firmware must be upgraded to v13.4 as a minimum to enable this bootloader upgrade to work. Contact nShield Support for details of obtaining the v13.4 version of firmware.

7.3.3.2. Upgrading bootloader

Once the primary firmware is at version v13.4 or later, the bootloader can be upgraded using the same hsmadmin upgrade command:

```
hsmadmin upgrade nShield5s-uboot-1-4-1.npkg --esn module-esn
```



Note: Once the bootloader version is upgraded, it is not possible to downgrade the bootloader to the previous version. The Primary and Recovery images can still be downgraded and upgraded independent of this bootloader version.

7.4. Upgrade a Connect XC image

If the Connect XC HSM is installed with image earlier than 12.45, 12.46, 12.50.4, or 12.50.7 it cannot be upgraded directly to the latest Connect image and needs to be first upgraded to an intermediate version. Any of the Connect image versions listed above can be used as an intermediate version. Please contact nshield.support@entrust.com for any other version of Connect image.

8. Compatibility

8.1. Supported hardware

This release is targeted at deployments with any combination of the following nShield HSMs:

- nShield 5s (Base, Mid, High)
- Solo XC (Base, Mid, High)
- nShield 5c (Base, Mid, High)
- Connect XC (Base, Mid, High, Serial Console)

8.2. Supported operating systems

This release has been tested for compatibility with the following operating systems:

Operating System	Solo XC	nShield 5s	Connect XC, nShield 5c
Microsoft Windows 11 x64	Y	Y	Y
Microsoft Windows Server 2022 x64	Y	Y	Y
Microsoft Windows Server 2022 Core x64	Y	Y	Y
Microsoft Windows Server 2025 x64	Y	Y	Y
Red Hat Enterprise Linux 8 x64	Y	Y	Y
Red Hat Enterprise Linux 9 x64	Y	Y	Y
Red Hat Enterprise Linux 10 x64	Y	Y	Y
SUSE Enterprise Linux 15 x64	Y	Y	Y
Oracle Enterprise Linux 8 x64	Y	Y	Y
Oracle Enterprise Linux 9 x64	Y	Y	Y

Security World v13.9.9 support is restricted to the x64 architecture. Additional mainstream x64-based Linux distributions other than those listed above may be compatible, however Entrust cannot guarantee this compatibility.

8.3. Supported operating systems for the Remote Administration Client (RAC)

The Remote Administration Client (RAC) has been tested for compatibility with the following operating systems:

Operating System
Microsoft Windows 11 x64
Apple Intel macOS 13 Ventura
Apple Intel macOS 14 Sonoma
Apple Intel macOS 15 Sequoia
Apple Intel macOS 26 Tahoe
Apple Silicon macOS 26 Tahoe

Operating System
Red Hat Enterprise Linux 8 x64
Red Hat Enterprise Linux 9 x64
Red Hat Enterprise Linux 10 x64
SUSE Enterprise Linux 15 x64

8.4. API support

8.4.1. Java

The versions in the table below are for both Oracle JDK and Open JDK.

Version	Supported
17	Y
21	Y
25	Y

8.4.2. Python

This lists the versions of Python that are supported.

Version	Supported
3.11	Y

8.5. Supported hypervisors and virtual environments

Network-attached HSMs

The nShield Connect XC and the nShield 5c are compatible with any virtual machine that is running a supported operating system.

PCIe HSMs

The following table lists the hypervisors and virtual environments that have been tested against PCIe HSMs for this release and whether they are supported or not:

Operating System	Solo XC	nShield 5s
Microsoft Hyper-V Server 2016	Y	Y
Microsoft Hyper-V Server 2019	Y	Y
Microsoft Hyper-V Server 2022	Y	Y
Microsoft Hyper-V Server 2025	Y	Y
VMWare ESXi 7.0	Y	N
VMWare ESXi 8.0	Y	Y
Citrix XenServer 8.2	Y	N

8.6. Supported compilers for Microsoft Windows C developers

Security World v13.9.9 C libraries for Windows were built using Visual Studio 2022 and have been compiled with the SDL flag. This makes them incompatible with older versions of Visual Studio. This applies primarily to static libraries.

Microsoft Windows developers should upgrade to Visual Studio 2022.

Version	Supported
2022	Y

9. Known and fixed issues

Reference	Scope	Status	Description
NSE-80224	Client-side	Resolved	Addressed an issue where the `C_Derive` command could return without releasing the session. **Resolved** in 13.9 client-side.
NSE-79929	Client-side	Resolved	It is now possible to import ML-DSA, ML-KEM and SLH-DSA public keys using `com.ncipher.km.nfkm`. **Resolved** in 13.9 client-side.
NSE-79737	Client-side	Resolved	Addressed an issue where the `cngsoak` utility would fail in a Strict FIPS world. **Resolved** in 13.9 client-side.
NSE-79724	Client-side	Resolved	Addressed an issue where the `hsc_codesafe` utility would raise an uncaught exception when SEE feature flags weren't enabled. **Resolved** in 13.9 client-side.
NSE-79472	Client-side	Resolved	Addressed an issue where forked PKCS#11 processes attempt to re-use the nCore connection during C_Initialize. **Resolved** in 13.9 client-side.
NSE-79401	Client-side	Resolved	Addressed an issue where the `auditd` service could fail to retrieve system logs and error with `nshield.audit.exceptions.SpoolerError` on Windows. **Resolved** in 13.9 client-side.
NSE-78597	Client-side	Resolved	Addressed an issue where an update to the RHEL 10.2 kernel broke the nShield Solo XC driver installation. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-78191	Client-side	Resolved	Addressed an issue where the `chkworld` utility would exit non-zero on success. **Resolved** in 13.9 client-side.
NSE-77984	Client-side and firmware	Resolved	Addressed an issue where CodeSafe 5 file processing ignored the `EncryptedContentHeader`. **Resolved** in 13.9 client-side and 13.8 firmware.
NSE-77954	Client-side	Resolved	Addressed an issue where `hsc_codesafe` would process all files in the `/opt/nfast/kmdata/cscerts/` directory regardless of file type. **Resolved** in 13.9 client-side.
NSE-77890	Client-side	Resolved	Addressed an issue where attempting to import a ML-KEM key using the `generatekey` utility would fail with `InvalidParameter`. **Resolved** in 13.9 client-side.
NSE-77832	Client-side	Resolved	Addressed an issue where the CodeSafe outputs did not contain the correct shared object (.so) files. **Resolved** in 13.9 client-side.
NSE-77618	Client-side	Resolved	Addressed an issue where the 5c `cs5monitor` could timeout and prevent Codesafe 5 from communicating with the HSM. **Resolved** in 13.9 client-side.
NSE-77588	Firmware	Resolved	Addressed an issue where the FIPS check in `DeriveMech_ECDHKA` was broken. **Resolved** in 13.8.5 (XC) / 13.8.6 (nShield 5) firmware.

Reference	Scope	Status	Description
NSE-77424	Connect	Resolved	Addressed an issue where the Connect unit would not upgrade firmware if build numbers matched. **Resolved** in 13.9 Connect images.
NSE-76421	Connect	Resolved	Addressed an issue where the Connect unit failed to respond correctly to Path MTU Discovery (PMTUD). **Resolved** in 13.9 Connect images.
NSE-76078	Connect	Resolved	Addressed an issue where the `getservlog` ApplianceCommand no longer functioned on Connect/5c units for log fetching. **Resolved** in 13.9 Connect images.
NSE-75862	Client-side	Resolved	Addressed an issue where `C_Decapsulate` and `C_Encapsulate` did not support `CKA_TOKEN=True`. **Resolved** in 13.9 client-side.
NSE-75763	Client-side	Resolved	Addressed an issue where the NFKM engine would silently fail if using a stale preload file. **Resolved** in 13.9 client-side.
NSE-75671	Client-side	Resolved	Removed the `pkcs11req` appname from `generatekey`. **Resolved** in 13.9 client-side.
NSE-75628	Client-side	Resolved	Addressed an issue with the help output for the `nethsmadmin` utility. **Resolved** in 13.9 client-side.
NSE-75208	Client-side	Resolved	Addressed an issue where the output of the `nfdiag` command on Windows contained extra backslashes. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-75207	Client-side	Resolved	Addressed an issue where the `nfdiag` command on Windows didn't contain a timestamp in the created `.zip` file. **Resolved** in 13.9 client-side.
NSE-75038	Client-side	Resolved	Addressed an issue where calling C_GenerateKey before C_Initialize would return CKR_ARGUMENTS_BAD. **Resolved** in 13.9 client-side.
NSE-75037	Client-side	Resolved	Addressed an issue where calling functions would segfault if called before C_Initialize. **Resolved** in 13.9 client-side.
NSE-75400	Client-side	Resolved	Addressed an issue where pkcs11extra.h erroneously referenced ML-DSA mechanisms after the 3.2 header adoption. **Resolved** in 13.9 client-side.
NSE-74960	Client-side	Resolved	Addressed an issue where `ulMinKeySize` and `ulMaxKeySize` were incorrect for multiple PKCS#11 mechanisms. **Resolved** in 13.9 client-side.
NSE-74499	Client-side	Resolved	Addressed an issue where `ckinfo` and `ckcheckinst` would return the wrong header version. **Resolved** in 13.9 client-side.
NSE-74363	Client-side	Resolved	Addressed an issue where nShield classic drivers (Solo XC) would failed to build on Linux Kernels 6.17 and 7.0. **Resolved** in 13.9 client-side.
NSE-74156	Client-side	Resolved	Addressed an issue where an assertion would occur when calling `perfcheck --diff` under certain circumstances. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-74125	Client-side	Resolved	The slotinfo for loadshared slots now includes the `CKF_HW_SLOT` flag. Softcard slots may be distinguished from OCS slots by the `CKF_REMOVABLE_DEVICE` flag. **Resolved** in 13.9 client-side.
NSE-74083	Client-side	Resolved	Addressed an issue where Java PublishedSEEWorld's getInitStatus() method would throw a null pointer exception for already successfully initialized Worlds. **Resolved** in 13.9 client-side.
NSE-74078	Client-side	Resolved	Removed the `embed` key type from `generatekey`. **Resolved** in 13.9 client-side.
NSE-73821	Connect	Resolved	Refined the `appliance-cli` help output. **Resolved** in 13.9 Connect images.
NSE-73585	Client-side	Resolved	Refined the error reporting for `cfg_remoteslots` when the importing module is a remote module. **Resolved** in 13.9 client-side.
NSE-72847	Client-side	Resolved	Addressed an issue where the `cs5 log get` command would report success even when logging is disabled. **Resolved** in 13.9 client-side.
NSE-72558	Client-side	Resolved	Renamed the nCore `FeatureInfo` flag that enables CodeSafe 5 on nShield 5 from `ExportCGEA` to `CodeSafe5`, so that the reported feature name reflects the functionality it enables. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-72542	Client-side	Resolved	Addressed an issue where SEElib_StartProcessorThreads() no longer crashes if nthreads is too high. **Resolved** in 13.9 client-side.
NSE-72539	Client-side	Resolved	Addressed an issue where 'pending job table full' / Status_ObjectNotReady error from SEElib_Transact() no longer occurs when many hundreds of threads are created. **Resolved** in 13.9 client-side.
NSE-72508	Client-side	Resolved	Addressed an issue where a CodeSafe 5 application could crash when C++ threads were used. This was due to the CMake build flags defined in the SDK not including the required flags for correct and consistent C++ builds. If not using CMake to build your CodeSafe 5 application, the C++ compiler and linker flags defined in the SDK's `codesafe-toolchain-nshield5-csee.cmake` file should be consulted to obtain the correct flags for your own build files. **Resolved** in 13.9 client-side.
NSE-72389	Client-side	Resolved	Addressed an issue where a `Failed to add a watch for /run/user/0/systemd/ask-password: Permission denied` warning would be displayed during installation of the product, or during the hardserver start/stop process on Red Hat Enterprise Linux 10 x64. **Resolved** in 13.9 client-side.
NSE-72241	Client-side	Resolved	Addressed an issue where objects could leak in the Java CoreKey class. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-72090	Connect 5c	Resolved	Addressed an issue where new remote client connections to a Connect or 5c would be rejected if the module failed after startup (this did not affect clients that were already connected when the failure occurred). This change supports remote recovery using a privileged client, using "nethsmadmin -r -m1" to reboot the appliance, or (in the case of 5c) using "nopclear-fail -r -m1" to attempt to retry after an error (e.g. to clear an SOS code). Note that if an error is cleared without a reboot, it may be necessary to restart the client hardserver (or remove and re-import the 5c using nethsmenroll) in order to reflect the updated state of no longer being Failed. This is not required if the appliance is rebooted instead. **Resolved** in 13.9 client-side.
NSE-71960	Client-side	Resolved	Addressed an issue where 'cnglist --show-sd' would not produce extra information correctly. **Resolved** in 13.9 client-side.
NSE-71959	Client-side	Resolved	Addressed an issue where NTE_NOT_FOUND errors would appear when listing CNG keys verbosely. **Resolved** in 13.9 client-side.
NSE-71927	Client-side	Resolved	Addressed an issue where csadmin image signing can fail when not all modules are usable within the current Security World. **Resolved** in 13.9 client-side.
NSE-71923	Client-side	Resolved	Fixed various issues with Connect XC and Connect 5c units. **Resolved** in 13.9 client-side.
NSE-71913	Client-side	Resolved	Addressed an issue where spurious errors would appear in the CodeSafe 5 logfile from SEEJob processing. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-71851	Client-side	Resolved	`csadmin` image signing subcommands now support specifying the application type (such as 'simple' or 'seeinteg') for Developer ID keys and Application Signing Keys. The previous default of 'simple' application type is retained for now for compatibility, but 'seeinteg' may be a more convenient choice for the Application Signing Key in order to support the use of the 'seeintegname' option in the 'generatekey' tool to generate keys that are restricted to the CodeSafe application. **Resolved** in 13.9 client-side.
NSE-71838	Client-side	Resolved	Fixed various issues with Connect XC and Connect 5c units. **Resolved** in 13.9 client-side.
NSE-71732	Client-side	Resolved	Fixed an issue where the automatic configuration of CodeSafe 5 via [codesafe] config section or the hsc_codesafe tool directly failed to stop existing applications on v13.4 firmware. [codesafe] configuration section and hsc_codesafe tool are now supported with v13.4 firmware when using the latest SecWorld and CodeSafe SDK. **Resolved** in 13.9 client-side.
NSE-71688	Documentation	Resolved	The Security Manual has been updated to state the limitations of the Connect/5c tamper log, and to emphasize the recommendation that Audit Logging should be enabled in new Security World creation as the primary security log mechanism. **Resolved** in 13.9 documentation.
NSE-71681	Firmware (5s only)	Resolved	Addressed an issue where a zero length salt could cause the HSM to fail. **Resolved** in 13.8.1 firmware.
NSE-71638	Documentation	Resolved	Updated the Security Manual to clarify the HSM form factors and the distinction between the Connect/5c appliance and the certified HSM inside it. **Resolved** in 13.9 documentation.

Reference	Scope	Status	Description
NSE-71637	Documentation	Resolved	Updated the Security Manual to clarify HSM decommissioning steps, especially that factory state is recommended for Connect/5c/5s modules, not just erasure of the Security World. **Resolved** in 13.9 documentation.
NSE-71635	Connect XC and 5c	Resolved	Fixed various issues with Connect XC and Connect 5c units. **Resolved** in 13.9 Connect Images.
NSE-71617	Connect XC and 5c	Resolved	Fixed various issues with Connect XC and Connect 5c units. **Resolved** in 13.9 Connect Images.
NSE-71565	Connect XC and 5c	Resolved	Fixed various issues with Connect XC and Connect 5c units. **Resolved** in 13.9 Connect Images.
NSE-71493	Client-side	Resolved	Addressed an issue where _nfpython3.so in the CodeSafe 5 SDK was not stripped of debug symbols, increasing the CodeSafe 5 container size. **Resolved** in 13.9 client-side.
NSE-71420	Firmware	Resolved	Addressed an issue where `CreateSEEConnection` would fail with `OSErrorErrno` for an invalid or stopped container ID. **Resolved** in 13.8 firmware.
NSE-71364	Client-side	Resolved	Addressed an issue where JCE key sizes for Edwards and XDH keys did not match the Java standard. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-71350	Connect	Resolved	Addressed an issue where the Connect unit cannot upgrade from v12.x Connect images. **Resolved** in 13.9 Connect images.
NSE-71308	Connect	Resolved	Fixed an issue where client licenses for 4 clients would not be applied correctly on Connect XC/5c in v13.6 or v13.7 Connect images. This issue is fixed in v13.6.12 (latest v13.6 LTS) and in v13.9 Connect images. **Resolved** in 13.9 Connect images.
NSE-71089	Firmware	Resolved	Addressed an issue to stop accepting elliptic curve domain parameters with certain types of unsupported fields. **Resolved** in 13.8 firmware.
NSE-70850	Client-side	Resolved	Addressed an issue where `csadmin sign` would succeed silently and not print a success message. **Resolved** in 13.9 client-side.
NSE-70765	Client-side	Resolved	Addressed an issue where `ncperftest` would not work with pre-created keys. **Resolved** in 13.9 client-side.
NSE-70686	Client-side	Resolved	Addressed an issue where the nShield 5s wouldn't be available for several minutes after a reboot. **Resolved** in 13.9 client-side.
NSE-70540	Firmware	Resolved	Addressed an issue where launcher does not check certificate policies for CS5 intermediate certs. **Resolved** in 13.8 firmware.
NSE-70375	Firmware (5s only)	Resolved	Addressed an issue with EllipticCurve ASN.1 inputs **Resolved** in 13.8 firmware.

Reference	Scope	Status	Description
NSE-70302	Client-side	Resolved	Addressed an issue where `cksotool` doesn't ask for FIPS auth in a sensible way. **Resolved** in 13.9 client-side.
NSE-70283	Client-side	Resolved	Addressed an issue where 'signextra' with non-FIPS mechanisms gives StrictFIPS140 error on load. **Resolved** in 13.9 client-side.
NSE-70255	Client-side and firmware	Resolved	`csadmin image presignask` no longer takes the CS5 image file as an argument. Instead, it requires only the `--package-name` parameter, which specifies the package name to sign. This allows the Developer ID to delegate signing to the ASK (Application Signing Key) for any version of that package name, rather than a single package instance. **Resolved** in 13.9 client-side and 13.8 firmware.
NSE-70232	Firmware (5s only)	Open	While under a prolonged period of heavy load generated by continuous signing or key generation operations using MLDSA 44, the 5s or 5c unit may fail with a `RC_SP_WRONG_PREAMBLE` error in the logs. Restarting the unit will restore it to a working state. **Issue first found** in 13.8 firmware
NSE-70194	Client-side	Resolved	Addressed an issue where harmless operations are not logged if a key has any restrictions. **Resolved** in 13.9 client-side.
NSE-70105	Client-side	Resolved	Addressed an issue where the CodeSafe XC NFKM libraries for GLIBC were missing from the CodeSafe installer. **Resolved** in 13.9 client-side.
NSE-70062	Client-side	Resolved	Fixed an issue where a CodeSafe 5 application would abort if more than 154 jobs were enqueued simultaneously. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-70007	Firmware	Resolved	Addressed an issue where KCDSA domain validation did not check parameters correctly. **Resolved** in 13.8 firmware.
NSE-69976	Client-side	Resolved	Addressed an issue where generatekey was missing AES import. **Resolved** in 13.9 client-side.
NSE-69898	Client-side	Resolved	Addressed an issue where the `hsc_codesafe` utility would log an error when no local module could be found. **Resolved** in 13.9 client-side.
NSE-69881	Client-side	Resolved	Addressed an issue where various PKCS11 functions were not thread-safe. **Resolved** in 13.9 client-side.
NSE-69925	Client-side	Resolved	Addressed various memory leaks in RQCard library. **Resolved** in 13.9 client-side.
NSE-69830	Client-side	Resolved	Addressed an issue where ch_checkkey() didn't reject non-FIPS keys in FIPS mode. **Resolved** in 13.9 client-side.
NSE-69623	Firmware	Resolved	Addressed RSA length inconsistencies. **Resolved** in 13.8 firmware.
NSE-69523	Client-side	Resolved	Addressed small memory leaks in C_Initialize, when run against a FIPS level 3 enforced Security World. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-69520	Client-side	Resolved	Fixed an issue on Windows where perfcheck called the deprecated Windows wmic tool, which may no longer be installed, to query CPU information for its report. **Resolved** in 13.7 client-side.
NSE-69503	Client-side	Resolved	Addressed an issue where the signers_transact() was broken in CodeSafe 5 Developer examples. **Resolved** in 13.9 client-side.
NSE-69326	Client-side	Resolved	Addressed an issue where sendcerts permits groups below the ciphersuite's minimum. **Resolved** in 13.9 client-side.
NSE-69076	Client-side	Resolved	Improved the CodeSafe 5 crash reporter so that some information would be provided even when a full backtrace was not available. **Resolved** in 13.7 client-side.
NSE-69053	Client-side	Resolved	Addressed an issue where the nShield 5s driver failed to report the version in dmesg. **Resolved** in 13.9 client-side.
NSE-69048	Client-side	Resolved	Added missing `NF_Copy_*` functions (for deep-copying nCore objects) to `seelib.a` for CodeSafe 5. **Resolved** in 13.9 client-side.
NSE-69020	Connect	Resolved	Addressed an issue where the Connect 5c upgrade will fail to upgrade if the time is not set on the module. Refer to [nShield5c-rtc] for more information. **Resolved** in 13.9 Connect images.

Reference	Scope	Status	Description
NSE-68919	Client-side	Resolved	The csadmin tool is now strict by default in requiring that the "launcher" service on the HSM has an attestation certificate. This certificate is only available in v13.5 and later firmware (and a factory state may be required to generate it if it is not present). If using a firmware version without support for attestation certificates (such as v13.4), the NC_SSH_ATTEST_CERT or NC_SSH_ATTEST_<esn> environment variables can be set in the environment of the csadmin tool to control the behaviour if there is a missing certificate. It can be set to IGNORE (connection proceeds silently), WARN (previous behavior prior to this change), or FAIL (connection will fail, new behavior). Setting NC_SSH_ATTEST_CERT=WARN or NC_SSH_ATTEST_CERT=IGNORE is suggested if using v13.4 firmware. It is recommended that factory state be done if necessary to generate the certificate if using v13.5 or later firmware if it is currently absent. **Resolved** in 13.9 client-side.
NSE-68682	Client-side	Resolved	Addressed an issue where `nethsmadmin --list-images` would return the wrong error message if the RFS IP was not specified. **Resolved** in 13.9 client-side.
NSE-68675	Client-side	Resolved	Addressed some performance and scheduling issues. **Resolved** in 13.9 client-side.
NSE-68534	Firmware	Resolved	Addressed an issue where legacy key-migration mistakes could lead to an inability to carry out further key-migration. **Resolved** in 13.8 firmware.
NSE-68179	Client-side	Resolved	Fixed an issue on Windows where an unwanted message box could appear relating to the TVD driver installation during a Security World software or Remote Administration software installation. **Resolved** in 13.7 client-side.
NSE-68093	Firmware	Resolved	Addressed performance issues with CodeSafe 5 administration operations. **Resolved** in 13.8 firmware.

Reference	Scope	Status	Description
NSE-68044	Client-side	Resolved	Addressed an issue where the csadmin utility failed to include the scope ID when reporting link-local addresses. **Resolved** in 13.7 client-side.
NSE-68007	Client-side	Resolved	Fixed an issue where incorrect parameters in client nCore commands (like wrong module number) were unnecessarily reported as errors in the hardserver log. **Resolved** in 13.7 client-side.
NSE-67930	Client-side	Resolved	Fixed an issue where CodeSafe 5 CSEE (SEElib) applications could fail with SIGPIPE in some cases. **Resolved** in 13.7 client-side.
NSE-67913	Firmware	Resolved	Addressed an issue with service restrictions and permissions. **Resolved** in 13.8 firmware.
NSE-67846	Client-side	Resolved	Fixed an issue where the nShield Audit Service could fail to correctly resume handling the export and expiry of system logs where an interruption had occurred during export on a previous run. **Resolved** in 13.7 client-side.
NSE-67839	Client-side	Resolved	Addressed an issue where DHPrivate 'xlength' checking is not exact. **Resolved** in 13.9 client-side.
NSE-67776	Firmware	Resolved	Addressed an issue where the `ch_generatekeypair` didn't always spot bogus key generation parameters. **Resolved** in 13.8 firmware.

Reference	Scope	Status	Description
NSE-67758	Firmware	Resolved	Addressed an issue where the firmware would provide incomplete validation error messages in response to the `csadmin` utility loading a CodeSafe 5 application. **Resolved** in 13.8 firmware.
NSE-67601	Firmware	Resolved	Addressed an issue where the incorrect BIOS code would be reported when the VCM would fail to start in single-tenant mode. **Resolved** in 13.7 firmware.
NSE-67579	Client-side	Resolved	Fixed an issue where output from nshieldaudit when printing to stdout rather than to file was not in JSON format as intended. **Resolved** in 13.7 client-side.
NSE-67248	Client-side	Resolved	Addressed an issue where the auditlog spooler service would log every 5 minutes when unconfigured. **Resolved** in 13.9 client-side.
NSE-67101	Client-side	Resolved	Addressed an issue on nShield 5c where it was not possible to delete a client's IP address in the config file after configuring it to not save the IP address. **Resolved** in 13.9 client-side.
NSE-66919	Client-side	Resolved	Addressed an issue where `nfkminfo` and Connect FPUI FIPS level reporting were misaligned. **Resolved** in 13.9 client-side.
NSE-66905	Documentation	Resolved	The documented set of allowed CodeSafe 5 system calls now reflects the set of system calls allowed by seccomp. **Resolved** in 13.7 documentation.

Reference	Scope	Status	Description
NSE-66800	Client-side	Resolved	Addressed an issue where some client-side CodeSafe developer libraries were shipped as source code rather than built as libraries. **Resolved** in 13.9 client-side.
NSE-66640	Client-side	Resolve	Addressed an issue where the `nfp_ioctl ensure reading: copy from user space failed` dmesg output would occur on some machines hosting nShield SoloXCs. **Resolved** in 13.9 client-side.
NSE-66437	Connect	Resolved	Made the Connect CLI command `setminvsn` more user-friendly. **Resolved** in 13.7 Connect images.
NSE-66432	Connect	Resolved	Addressed an issue with `hsmdiagnose` where a test was incorrectly skipped. **Resolved** in 13.7 Connect images.
NSE-66415		Open	The appliance-cli gethsmstatus command returns a 'Failed to retrieve status' error when executed against Legacy FIPS Connect image. This means the version information for the Legacy FIPS Connect image cannot be retrieved at this time. **Issue first found** in 13.6
NSE-66256	Client-side	Resolved	Addressed an issue where the message "Failed to parse last log data from current log" would be displayed in the nshieldauditd logfile. **Resolved** in 13.7 client-side.

Reference	Scope	Status	Description
NSE-66232	Firmware	Resolved	Addressed a firmware issue which prevented CodeSafe 5 applications built with 13.4 SDK from working on later versions of firmware. Applications built with 13.4 SDK will work on 13.7 and later firmware, but they cannot run on 13.5 firmware which does not have this fix. **Resolved** in 13.7 firmware.
NSE-65799	Client-side	Resolved	Addressed an issue where a stack trace would be displayed during installation on SLES12 platforms. **Resolved** in 13.7 client-side.
NSE-65310	Client-side	Resolved	Addressed an issue where encryption with CKM_AES_CTR in PKCS#11 failed if used with a token key that had not been loaded on the module. **Resolved** in 13.9 client-side.
NSE-65292	Firmware	Resolved	Addressed an issue where a Status_Failed message would occur instead of Status_DecryptFailed with RSAUnwrap and AES Key unwrapping under certain circumstances. **Resolved** in 13.7 firmware.
NSE-65229	Firmware	Resolved	Addressed an issue where DeriveMech_PublicFromPrivate doesn't work with Ed448Private. **Resolved** in 13.7 firmware.
NSE-65109	Firmware	Resolved	Addressed an issue where the Solo XC was too enthusiastic to clear the module from the clear button. **Resolved** in 13.7 firmware.
NSE-64992	Client-side	Resolved	Addressed an issue where the `ncperftest` utility could crash if an unreasonable queue size is set. **Resolved** in 13.7 client-side.

Reference	Scope	Status	Description
NSE-64885	Client-side	Resolved	Addressed an issue where the CONNECTION ERROR: Unable to connect to 'monitor' failure would occur when multiple clients were attempting to connect to the monitor service. **Resolved** in 13.7 client-side.
NSE-64592	Documentation	Resolved	Addressed an issue where the M_AESmGCM HTML docs omitted the ciphertext format. **Resolved** in 13.7 documentation.
NSE-64625	Client-side	Resolved	Addressed an issue where HSM Pool Mode would not work in PKCS #11 with a v13 client-side and older v12 firmwares. **Resolved** in 13.9 client-side.
NSE-64570	Client-side	Resolved	`nfkmattest` will now display the filename if a problem is encountered when reading the file. **Resolved** in 13.9 client-side.
NSE-64525	Client-side	Resolved	Addressed an issue where nfkmverify didn't accept keys which could perform ECIES unwrapping. **Resolved** in 13.9 client-side.
NSE-64438	Firmware	Resolved	Addressed an NVMWearLevel issue for Solo XC and nShield 5s units. **Resolved** in 13.7 firmware.
NSE-64409	Client-side	Resolved	Fixed an issue which prevented later CodeSafe SDKs from running on v13.4 firmware. Rebuilding application with the latest CodeSafe SDK will enable it to run on v13.4 firmware. This re-enables support for applications written in C. For Python support, the v13.4 CodeSafe SDK must continue to be used with v13.4 firmware. Newer CodeSafe SDK is supported on v13.5 and later firmware in all cases. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-64304	Client-side	Resolved	Addressed an issue where D3S certificates appear in ncoreapi's stderr. **Resolved** in 13.9 client-side.
NSE-63892	Client-side	Resolved	Addressed an issue where generated nCore HTML pages could be missing. **Resolved** in 13.7 client-side.
NSE-63502		Open	When using KeySafe5 with the agent on the Connect the following error will populate the logs 'Command failed: monitor codesafestats get-all'. Users should increase the codesafe_update_interval using the ks5agent command via the Connect CLI. ks5agent cfg codesafe_update_interval=48h If you wish the logs to be cleared then enabling the Audit tooling will expire the system logs containing the above error. **Issue first found** in 13.6
NSE-63449	Client-side	Resolved	Addressed an issue in PKCS#11 where the following error would be reported: 'Key generation certificate with no private/secret key?' **Resolved** in 13.7 client-side.
NSE-63444	Client-side	Resolved	Addressed an issue in PKCS#11 where confusion between nShield and PKCS#11 key type enum values could cause a 'NFBER_Encode_Octet_BitStr_Key failed for len' error. **Resolved** in 13.7 client-side.
NSE-63091	Client-side	Resolved	Fixed an issue where the C_GetAttributeValue return value could be overwritten. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-62984	Client-side	Resolved	Addressed an issue in `nethsmadmin` where the feature file help was misleading. **Resolved** in 13.9 client-side.
NSE-62533	Client-side	Resolved	Addressed an issue in PKCS#11 where SELinux would prevent CodeSafe 5 applications from binding on some ports. **Resolved** in 13.7 client-side.
NSE-62267	Client-side	Resolved	Addressed an issue where multiple hardware failures could occur on Edge units. **Resolved** in 13.9 client-side.
NSE-61967	Client-side	Resolved	Addressed an issue where the tar utility would be killed by seccomp when used within a CodeSafe 5 application. **Resolved** in 13.7 client-side.
NSE-61966	Client-side	Resolved	An issue has been fixed where, if a CodeSafe 5 application created files on its local disk, 'csadmin destroy' reported an error when trying to remove those files. **Resolved** in 13.9 client-side.
NSE-61540	Client-side	Resolved	Addressed an issue where the CS5 Compatibility Layer would not stay listening for incoming connections. **Resolved** in 13.7 client-side.
NSE-61148	Firmware	Resolved	Addressed an issue where the init log is not created by replacement Python code as it should be. **Resolved** in 13.7 firmware.
NSE-61033	Firmware (5s only)	Resolved	Addressed an issue where deprecated options were reported in the nShield 5s system logs. **Resolved** in 13.7 nShield 5s firmware.

Reference	Scope	Status	Description
NSE-60936	Firmware	Resolved	Addressed an issue where CodeSafe can lose trace data. **Resolved** in 13.7 firmware.
NSE-60779	Client-side	Resolved	Fixed an issue where the nShield 5c would fail to Factory State if the nShield 5s system log was full. **Resolved** in 13.9 Connect images.
NSE-60554	Client-side	Resolved	Addressed an issue where TUAK and Milenage session key generation performance had decreased due to the need to generate key generation certificates at the point of key generation. This has been resolved by adding a new PKCS#11 environment variable: CKNFAST_SESSION_TO_TOKEN, this is enabled by default. The default behaviour is to generate session keys without Key Generation Certificates. This can be disabled by setting CKNFAST_SESSION_TO_TOKEN=0. **Resolved** in 13.7 client-side.
NSE-59598	Client-side	Resolved	Fixed an issue where RQCard used in conjunction with nflog could cause a segmentation fault. **Resolved** in 13.9 client-side.
NSE-59584	Client-side	Resolved	Addressed an issue where it wasn't possible to generate a CodeSafe 5 CSR using the `csadmin` utility on Windows systems if the OCS has a passphrase set. **Resolved** in 13.9 client-side.
NSE-59281	Client-side	Resolved	Addressed an issue where CodeSafe developer id certificates can be issued for RSA keys and the issued RSA keys can now sign images. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-57030	Client-side	Resolved	On Linux, the sshadmin client key for nShield 5s is now backed-up automatically to /root/.ssh/id_nshield5_sshadmin as a precaution against /opt/nfast/services/client directory being deleted. This backup is restricted to the local machine by default. It is recommended on both Windows and Linux to backup the sshadmin key if using nShield 5s. If it may be necessary to move the HSM to a different machine (or to reinstall the OS) at a later stage, the key should be backed up with the "hsmadmin keys backup --passphrase" option so that it is protected by a passphrase rather than being restricted to the local machine and OS installation. **Resolved** in 13.9 client-side.
NSE-55780		Open	Starting a CodeSafe 5 application on an nShield 5c produces the message "Could not find nshield network interfaces for service discovery" in the verbose output. **Issue first found** in 13.4
NSE-55428		Open	Building classic CodeSafe examples fails with older compiler. **Issue first found** in 13.4
NSE-55425	Firmware	Resolved	Addressed an issue where 'Unable to perform operation due to service interdependency lock' was reported when using the `csadmin` utility. **Resolved** in 13.7 firmware.
NSE-55378		Open	Minor inconsistency when enabling autostart via csadmin config.
NSE-55142		Open	From 13.4 keys generated using ckrsagen will now produce a warning using nfkmverify, this is due to stricter policy enforce on unwrap permissions. To overcome this use CKA_UNWRAP_TEMPLATE when generating PKCS#11 keys. **Issue first found** in 13.4

Reference	Scope	Status	Description
NSE-55136	Client-side	Resolved	Fixed an issue where offline produced CodeSafe 5 image signatures would fail CreateSEEConnection. **Resolved** in 13.9 client-side.
NSE-53090	Client-side	Resolved	Fixed an issue where using `nethsmadmin -f` provided the wrong path to use when applying features. **Resolved** in 13.9 client-side.
NSE-52456	Firmware (5s only)	Resolved	Addressed an issue where hsmadmin settime would leave the module around 2 seconds behind the host. **Resolved** in 13.7 nShield 5s firmware.
NSE-52302	Firmware (5s only)	Resolved	Addressed an issue with impath command sanitization. **Resolved** in 13.8.1 firmware.
NSE-50848	Client-side	Resolved	Fixed an issue where `ckmechinfo` would advertise wrap support that didn't work. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-50548	Client-side	Resolved	Fixed an issue where the `seemachtype` field in the `EnquiryDataSix` response from the `NewEnquiry` command used the `SEEMachineType` enumeration type directly rather than the `Word` type, meaning that older clients could fail to communicate with newer HSMs that used new values unknown to the client, even where this value was not relevant to the application. The `Word` type is now used so that clients will tolerate new SEE machine types being introduced in future. This does not fix the issue for historic clients. There is no change to the nCore wire protocol, this is a library change only. C/C++ applications should be unaffected by the type change in practice, but Java applications that referenced this field that wish to print the name of the SEE machine type should now use `NFUtils.convertEnumValue(six.seemachtype.value, M_SEEMachineType.class)` instead of `M_SEEMachineType.toString(six.seemachtype)`. In Java, the type of `M_EnquiryDataSix.seemachtype` has changed from `long` to `M_Word`, which is not binary compatible. Java applications that use this field and were compiled against `nCipherKM.jar` from a release earlier than v13.9.3 fail with `java.lang.NoSuchFieldError` when they access the field with v13.9.3 or later. They must be updated to use `seemachtype.value` and recompiled, after which they require `nCipherKM.jar` from v13.9.3 or later. **Resolved** in 13.9 client-side.
NSE-50050	Client-side	Resolved	Fixed an issue where the `nfkmverify` utility would not reject wrapping keys with the decrypt permission set. **Resolved** in 13.9 client-side.
NSE-49263	Client-side	Resolved	Fixed an issue where `mkaclx` printed an unclear error when a malformed ident string was specified on the command-line. **Resolved** in 13.9 client-side.
NSE-48991	Client-side	Resolved	Addressed an issue where nfkmutils.loadkey did not support softcards. **Resolved** in 13.7 client-side.
NSE-43472	Client-side	Resolved	Addressed various issues with nfkmutils.loadkey. **Resolved** in 13.7 client-side.

Reference	Scope	Status	Description
NSE-42031	Firmware (XC only)	Resolved	Addressed a gradual increase in memory usage on nShield Solo XC modules. **Resolved** in 13.7 nShield Solo XC firmware.
NSE-41205	Firmware (XC only)	Resolved	An issue has been fixed that can cause a Solo XC or Connect XC HSM to enter an SOS state after many days of running. The issue would have generally manifested as an SOS-HV or SOS-HRTP, but other SOS codes are possible. A number of "SpiRe-tries" as reported by stattree utility may precede the failure. **Resolved** in 13.7 nShield Solo XC firmware.
NSE-48073		Open	Connect+ models running software earlier than v12 must first be upgraded to a v12 version before being upgraded to v13. See section Upgrade from previous releases for more details. **Issue first found** in 13.3
NSE-42017	Connect	Resolved	Fixed various issues with Connect XC and Connect 5c units. **Resolved** in 13.9 Connect images.
NSE-39031		Open	In Security World v12.10 a compliance mode was added to the Connect to allow compliance with USGv6 or IPv6 Ready requirements. **Issue first found** in 12.80
NSE-38156	Client-side	Resolved	Addressed an issue where Linux SNMP install depended on the `netstat` utility. This has now been replaced with the `ss` utility. **Resolved** in 13.9 client-side.
NSE-36086	Client-side	Resolved	Addressed an issue where OpenSSH did not enable TCP_NODELAY resulting in latency spikes in CodeSafe 5 communica-tion. **Resolved** in 13.7 client-side.

Reference	Scope	Status	Description
NSE-35974	Firmware	Resolved	Addressed an issue where `nvram-sw` could not delete all NVRAM files. **Resolved** in 13.8 firmware.
NSE-73249	Firmware	Resolved	Addressed an issue where files written by a CodeSafe 5 application within its container became inaccessible after a reboot of the HSM. Note that application files must be written to the `/home/codesafe` directory in order to be persisted. **Resolved** in 13.8.4 firmware.
NSE-35520	Client-side	Resolved	Addressed an issue where the `nfkmverify` utility would reject future impath groups. **Resolved** in 13.9 client-side.
NSE-32255	Client-side	Resolved	Addressed an issue where running `nopclearfail --wait` with an nShield Connect would not wait. **Resolved** in 13.9 client-side.
NSE-32255	Client-side	Resolved	Addressed an issue where the `ncperftest` help text omitted option to "test with an existing key". **Resolved** in 13.9 client-side.
NSE-28606		Open	Entrust do not recommend migrating keys to non-recoverable worlds since it would then be impossible to migrate the keys in future should the need arise. If keys are migrated into a non-recoverable world then it is not possible to verify OCS and softcard protected keys directly with nfkmverify. The OCS or softcards must be preloaded prior to attempting to verify the keys.
NSE-26829	Client-side	Resolved	Addressed an issue where the reserved C++ keyword `export` was used as a field name in `M_Command.args.export` and `M_Reply.reply.export`. This affected applications using headers that pulled in the nCore types, such as `nfastapp.h` or `seelib.h`. By default, the field will now be renamed using the pre-processor to `exportcmd` when compiling with a C++ compiler. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-25401		Open	When installing 12.60 on a Dell XPS 8930 PC, a "Files in Use" screen may be displayed where it prompts to close down and restart Dell, Intel and NVIDIA applications. This can be ignored. **Issue first found** in 12.60
NSE-24335		Open	This issue applies to 12.50.11 XC firmware only. As a result of work to improve the upgrade experience with Solo XC it is necessary to add the following lines to /etc/vmware/passthru.map for successful operation of Solo XC in an ESXi environment: # Solo XC 1957 082c link false **Issue first found** in 12.50
NSE-24026	Client-side	Resolved	Addressed an issue where the `nvram-sw` application read and write command did not require the `-n` option to function. **Resolved** in 13.9 client-side.
NSE-23982		Open	While resetting password if user enters incorrect password, cli prompt prints lone "I". This is where login handler program would print "Incorrect password for cli" message. Only "I" gets through the wire in time due to slow baud rate of the connection. This error is trivial and is only seen at the first log in during password reset. **Issue first found** in 12.50
NSE-23332	Client-side	Resolved	Addressed confusing help message when calling `rfs-setup --gang-client`. **Resolved** in 13.9 client-side.
NSE-22692	Client-side	Resolved	Addressed an issue where the `rocs` utility would truncate key names that were more than 24 characters long. **Resolved** in 13.9 client-side.

Reference	Scope	Status	Description
NSE-22484	Client-side	Resolved	Addressed an issue where the `generatekey` utility would ignore preloaded FIPS auth. **Resolved** in 13.9 client-side.
NSE-14406		Open	In the Connect config file the remote_sys_log config entry implies multiple entries can be defined but only one remote sys-log server can be configured. **Issue first found** in 12.50
NSE-8568	Client-side	Resolved	Addressed an issue on Linux platforms where the `edgeHandler.sh` script failed to cope with more than 1 serial_dtpp_device line in the configuration file. **Resolved** in 13.9 client-side.
NSE-7446	Client-side	Resolved	Addressed an issue where the PKCS#11 CMAC output length was wrong. **Resolved** in 13.9 client-side.
NSE-4551	Client-side	Resolved	Addressed an issue where unregistering the CNG providers using the `cngregister` utility would complain that it failed to delete the local machine key. **Resolved** in 13.9 client-side.